

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number N5D007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 480-3718	4. Manifest Tracking Number 008091340 FLE				
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2845 North New York Street Wichita, KS 67219 Generator's Phone: (316) 289-7400			Generator's Site Address (if different than mailing address) SAME						
6. Transporter 1 Company Name NEIRA INC			U.S. EPA ID Number IND984868406						
7. Transporter 2 Company Name			U.S. EPA ID Number						
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 68145 Facility's Phone: (308) 235-4912			U.S. EPA ID Number NE0981728813						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
			No.	Type					
	1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III		1	CM	EST 12	Y	D004	D005	D007
							D008	D036	D040
14. Special Handling Instructions and Additional Information 1. CH181506X05 ERG171 TR# CHRT# 25026									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Sun 1/20/15			Signature [Signature]			Month Day Year 1/20/15			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:									
17. Transporter Acknowledgment of Receipt of Materials									
Transporter 1 Printed/Typed Name Chris Shumate			Signature [Signature]			Month Day Year 1/29/15			
Transporter 2 Printed/Typed Name			Signature			Month Day Year			
18. Discrepancy									
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number									
Facility's Phone:									
18c. Signature of Alternate Facility (or Generator) Month Day Year									
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H040		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name			Signature			Month Day Year			

B1501118

X0 X09422595-029

SC PPW 12/1/2008

Form Approved. OMB No. 2050-0039

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008091340 FLE			
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219			Generator's Site Address (if different than mailing address) SAME					
Generator's Phone: (316) 269-7400								
6. Transporter 1 Company Name NEIRA INC			U.S. EPA ID Number IND984868406					
7. Transporter 2 Company Name			U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145			U.S. EPA ID Number NED981723513					
Facility's Phone: (308) 235-4012								
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
		No.	Type					
X	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III	MS	EST	10	Y	D004	D005	D007
		1	cm	12	Y	D008	D039	D040
	2.							
	3.							
	4.							
14. Special Handling Instructions and Additional Information 1. CH831506X0B ERG#171 TR# ICH CHMT# 25026								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Jim Tyson			Signature <i>[Signature]</i>			Month Day Year 12/28/15		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name Cris Shumate			Signature <i>[Signature]</i>			Month Day Year 1/29/15		
Transporter 2 Printed/Typed Name			Signature			Month Day Year		
18. Discrepancy								
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
Manifest Reference Number: _____								
18b. Alternate Facility (or Generator) U.S. EPA ID Number								
Facility's Phone: _____								
18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H040		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Thomas Clark			Signature <i>[Signature]</i>			Month Day Year 01/28/15		

B150118

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008091340 FLE					
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219			Generator's Site Address (if different than mailing address) SAME							
6. Transporter 1 Company Name NEIR INC			U.S. EPA ID Number IND984868406							
7. Transporter 2 Company Name			U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145			U.S. EPA ID Number NED981723513							
Facility's Phone: (308) 235-4012										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes			
			No.	Type						
	x	1 NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III	1	OT	EST 16	Y		D004	D005	D007
								D008	D039	D040
14. Special Handling Instructions and Additional Information 1 CH831506X08 ERG#171 TR# CHIT# 25026										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generator's/Offor's Printed/Typed Name JIM TYSON					Signature <i>[Signature]</i>		Month Day Year 12/28/15			
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____									
	Transporter signature (for exports only): _____									
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials									
	Transporter 1 Printed/Typed Name Cris Shumate					Signature <i>[Signature]</i>		Month Day Year 1/29/15		
	Transporter 2 Printed/Typed Name					Signature		Month Day Year		
DESIGNATED FACILITY	18. Discrepancy									
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
	Manifest Reference Number: _____									
	18b. Alternate Facility (or Generator)					U.S. EPA ID Number				
	Facility's Phone: _____									
	18c. Signature of Alternate Facility (or Generator)					Month Day Year				
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
	1. H040		2.		3.		4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
	Printed/Typed Name Thomas Clark					Signature <i>[Signature]</i>		Month Day Year 01/28/15		



2247 South Highway 71
Kimball, NE 69145

TEL 308-235-4012
FAX 308-235-4307
www.cleanharbors.com

DATE: 1/28/2015

MANIFEST: 008091340FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department